



Mining Equipment Sale Processing Equipment, CAT Yellow Gear & Motor Vehicles



AUCTION CATALOGUE

AUCTION SALE TO BE HELD ON THE SITE & BROADCAST LIVE ONLINE

1450 WOODSTOCK ROAD, SAPPHIRE NSW 2360 (FOLLOW SIGNAGE)

TUESDAY 5TH FEBRUARY 2018 AT 11AM AEDT

UNDER INSTRUCTIONS FROM:



IN THE MATTER OF: BOND RESOURCES PTY LTD (IN LIQUIDATION)

INSPECTION: MONDAY 4TH FEB 9AM - 4PM, AND DAY OF SALE FROM 8AM

ENQUIRIES: PATRICK SYMONS 0416 151 506

NOTES: A BUYERS PREMIUM OF 10% + GST WILL APPLY TO ALL LOTS SOLD

HAMMER PRICE IS GST EXCLUSIVE

SOME LOTS MAY BE SUBJECT TO REDEMPTION

\$100 CASH OR CREDIT CARD DEPOSIT REQUIRED ON REGISTRATION

ALL LOTS MUST BE REMOVED BY 4PM 10TH FEB 2019

EVERYTHING MUST BE SOLD!

LOT	QTY	DESCRIPTION	RISK CODE
1	1	Spill Pallet - With 44 Gallon Drum and Assorted Loose Drums of Oil, Manual Drum Pump (Buyer Must Take All)	7, 15
2	1	2 x Toolboxes - Steel Fabricated Lockable, Approx. 1000 x 300 x 300mm	7
3	1	Allowance for Items - Comprising of 7 x New 2 by 4 Lengths of Timber, Box of Assorted Bolts, Hydraulic Valve, Ramset Gun, Motor, Trailer Winch and 1 x Aluminium Straight Edge (Buyer Must Take All)	7, 15
4	1	2 x Tyres - 1 x Good Year Wrangler R16/LT265-76 30% Tread on Alloy Rim And 1 x R16/198/85 0% Tread (Buyer Must Take All)	7
5	1	Flat Hose - 5 Reels Approx. 80Mtrs, No Fittings, Blue in Colour	7
6	1	Allowance for Grease Guns - 4 In Boxes, 2 x Standard Guns	7, 15
7	1	Allowance Parts - Assorted Air Filters, Fuel Filters & Bearing Units (Inspection Recommended)	7
8	1	Allowance for Electrical Components - Including Cable, Various Lengths and Gauge, and Switch Box, 3Ph and 1Ph (Inspection Recommended)	2, 7
9	1	Air Hose - Red In Colour, With Fittings	7, 18
10	1	Lifters - 2 x Manual Lifters, Yellow In Colour, (Use Unknown)	7, 19
11	1	Air Receiving Tank - Approx. 1400mm	7, 18
12	1	Safety Cones & Barriers - Approx. 10 x Cones & 6 x Extendable Barriers	3, 7
13	1	Concrete Rio Cradles, Plastic - To Box	7
14	1	Aqua Blue Pump/Motor Part, On Pallet New	7
15	1	Allowance For Items Including - Tools To Crate Including Snips, Files and Saw, 1 x Bucket Of Bolts And Nuts, 1 x Wire Reel, 1 x Hose & 1 x Fan (Buyer Must Take All)	2, 7
16	1	Air Compressor - Renegade Industrial, HD 500, 3 Cyl 3 Phase. On Horizontal Receiver	2, 5, 7, 16, 18
17	1	Spray Unit - Aqua Spray Systems Back Pack Unit (Used Weed Killer)	7, 15
18	1	Assorted Items - Including Weed Killer, Spray Paint Ladder and Stool (Buyer Must Take All)	7, 15
19	1	Allowance for Scrap Items - Including Excavator Bucket Toes, 3 Phase Motors, Hydraulic Valve Body, Pump Parts and Other Assorted Items to Table. And Area	2, 7
20	1	Steel Work Bench - Heavy Duty, Steel Fabricated Approx. 3500 x 1500, Including Vice and Contents, As Is (Buyer Must Take All)	7
21	1	Cabinet - First Aid Cabinet, Steel Fabricated, With Chairs and Contents (Buyer Must Take All)	7, 12
22	1	Allowance Of Tyres - 2 x Michelin 29.5/26 Worn, 13 x Assorted Tyres (Buyer Must Take All)	7
23	2	44 Gallon Drums	7, 15
24	1	Allowance for Pumps to Area, Parts only	2, 7
25	1	Magnetic Separator - 1x Rotating Magnetic Separator, Riel Magnetics Australia	1, 2, 3, 4, 6, 7, 9, 14, 15, 20, 28
26	1	GP Bucket - Ingersoll Rand, DOM 2010, 2100. Suit Bobcat	7, 16, 17
27	1	Trommel - 1x Trommel Screen & Base, Steel Fabricated	6, 7
28	1	Emulsion Tank - 2000L	7, 15
29	1	Steel Mesh Screens Steel Plates & Components to 7 Pallets	7
30	1	Pump - Selwood, D150 - Rapid Response, 16310 Hours, Operational Condition Unknown	2, 6, 7, 10, 30
31	1	Scrap Steel - 4 x Pallets of Assorted Steel Components	7
32	1	1x Steel Cage of Conveyor Rollers, Rusted, 2 x Part ROLLS OF Belt	7, 29

LOT	QTY	DESCRIPTION	RISK CODE
33	1	Steel Frame - Steel Frame to Suit Fintech Screen	7
34	1	Electrical Cabling - Assorted Lengths and Gauge Cable to Pallet	2, 7
35	1	Steel Feed Bin - Steel Fabricated, Approx. 2500 x 1000mm, Bottom Out Feed	7
36	1	Steel Chanel - Approx. 11 Lengths, Approx 4500mm L Each	7
37	1	Steel Frame - Steel Fabricate Frame, Disassembled	7
38	1	Steel Panels And Frame - Steel Mesh Safety Panels, with Steel Frame	7
39	1	Steel Frame - Steel Frame Pieces in Green, Originally Formed Part of Green Conveyor Now Disassembled	7, 29
40	1	Steel Frame - --Steel frame In Grey, Approx. 4,000mm L	7
41	1	Steel Piping - Assorted Steel Piping	7, 30
42	1	Work Bench, Steel Fabricated, 4000 x 1800 x 1000 Approx.	7
43	1	2x Steel A-Frame Pieces	7
44	1	1x Adjustable Height Outfeed Chute	7
45	1	Shipping Container - 40ft, Sealed, 10ft Internal Besa Block Section, Steel Frame Door, S/N: 4340780	2, 7, 13
46	1	Lockers - Steelco 12 x Steel Construction, Single Bay	7
47	1	Safe - Sandleford, Electronic Combination Approx. 1000 x 300 x 400mm (Combination available and can be changed)	7
48	1	Rough Stones & Sapphires, Uncut and Unsorted - 2 x 44 Gallon Drums	7
49	1	Rough Stones & Sapphires, Uncut and Unsorted 26 Buckets	7
50	1	Dismantled Process/Wash Plant Was Box/Dump Bin - 60m3 Wash Box Assembly, Inc. Nozzle, with Hydraulic excavator grab. 1 x Motor Control Cubical For Screening Plant	1, 2, 6, 7, 13, 18, 19, 20, 23, 29
51	1	Feed Hopper - 1 x Tile Lined Conical Hopper with Outfeed Conveyor to Base, With Steel Frame With Skid Base	1, 2, 6, 7, 13, 18, 19, 20, 23, 29
52	1	Surge Hopper - 1 x 20m3 Surge Hopper, Steel Fabricated on Frame, With Hydraulic Lower Outfeed Gate	6, 7, 13
53	1	Concrete Counter Weight - Weight Not Known	7
54	1	Hopper and Frame - Steel Fabricated Frame and Hopper for De Watering Screen	6, 7, 13
55	1	Piping - Assorted Diameter Length and Diameter Piping 8 & 5 Inch	7, 13, 30
56	1	Steel Stair Case - Steel Fabricated Stair Case and Platform, with 1 x Flight of Stairs and 2 x TECO 3 ph. Motor, 20kw	6, 7, 13
57	1	Conveyor - Steel Latic Fabricated Green In Colour, approx. 25m L With Upper and Lower Rollers and Attached Steel Walk Way. Approx. 1200mm Conveyor Width, 1 x 22kw 3ph TECO Motor, with Infeed and Outfeed Hoppers	6, 7, 13, 29
57A	1	Conveyor- Steel Fabricated Blue in Colour, 1000mm wide Belt, frame Cut in two, 1 x 20kw RCG Motor	6, 7, 13, 29
58	1	Trommel Screen - Trommel Screen Frame with Motor, Screen Removed. With Steel Super Structure, 3ph Motor, Platform Approx. 6 x 3m	1, 2, 6, 7, 13, 18, 19, 20, 23, 29
59	1	Pump - Warman, Type: SCB/6, ESC6013 - C1	2, 7, 9, 13, 16, 30
60	1	Pump - Warman, 10/8m TECO 3 Motor, No Plate	2, 7, 9, 13, 16, 30
61	1	3 Phase Motor, Yellow in Colour, Mechtric NSW, 11KW, 50Hz, Components Missing. Possible from part of The Process Plant When Decommissioned & 1 x Ajax Pumps, E50-76 M11, 210, 130, 11Kw, Imp Dia, 170mm, Poor Condition, Components Missing	2, 7, 9, 13, 16, 30
62	1	Assorted Motors Comprising: 1 x 3 Phase Motor, Grey and Rust in Colour, Poor Condition. Components Missing; 1 x WEG, 3 Phase Motor, 200L 982, 50Hz, 30Kw, 415V, Poor Condition, 1 x Ajax Pump	2, 7, 9, 13, 16, 30

LOT	QTY	DESCRIPTION	RISK CODE
63	1	Wash Screen/ De-Watering Screen - Honert, VSW 1-1800/3700 - RPM 430, DSW 1800mm x 3700mm, S/N: 60407/4026/1118	1, 2, 6, 7, 13, 18, 19, 20, 23, 29
64	1	Wash Screen/ De-Watering Screen - Allis, White Painted, No Stand, S/N: 3124, Bearing Replaced in the Last 24 Months	1, 2, 6, 7, 13, 18, 19, 20, 23, 29
65	1	Steel Fabricated Frame - 4 x Posts With Cross Beams	7
66	1	Percussion Screen - FinTech 570 Colour: Blue Engine Make: Caterpillar Horsepower: Diesel Hours: 8014 Tyre Wear Remaining: 60% 1x Conveyor/Wash Conveyor, Blue in Colour	1, 2, 3, 4, 5, 7, 9, 17, 19, 20, 26, 27, 28, 31
67	1	Hammer Mill - Power engineering and MFG. AD-17 Crusher, DOM 1996, Not currently installed on Fintech Machine, S/N: No Build Plate Visible	1, 2, 3, 4, 5, 7, 9, 17, 19, 20, 26, 27, 28, 32
68	1	Excavator - Caterpillar, 345D LME - YOM: 2010 Enclosed Cabin, Air Conditioned ROPS/FOPS: Yes Colour: Yellow Engine Make: 2236 Diesel Hours: 9,855 Piped for Hammer: Yes Tyre Wear Remaining: 80% Notes: Hand Rails, Reverse Camera, Beacon Lights, Quick Hitch, Fire Suppression, S/N: CAT0345DLBYC00157	1, 2, 3, 4, 5, 7, 9, 17, 19, 20, 26, 27, 28, 31
68A	1	Excavator Bucket - ARS, K400 - GP Bucket to Suit 35T Excavator, 1.91m, 2200mm Wide, S/N: ARS201506240872	7, 17, 19
69	1	Grader - Caterpillar, 120G - YOM: 1988 Enclosed Cabin Colour: Yellow Engine Make: Caterpillar Engine Model: 3304DI Diesel Hours: 8,646 (Showing) Tyres Poor Major Rust Notes: Not WMS Compliant Farm Use Suitable, 1 x Door Removed Cond. Rego: 17176D (NSW), S/N: 11WO1271	1, 2, 3, 4, 5, 7, 9, 17, 19, 20, 26, 27, 28, 31
70	1	Articulated Dump Truck - Caterpillar, 740 - YOM: 2010 Unit/Fleet No: 4T003 Enclosed Cabin, Air Conditioned ROPS/FOPS: Yes Colour: Yellow Diesel Hours: 12,839 (As of 11/2017) Tyre Wear Remaining: Front - Poor, Rear-Good Minor Rust Notes: Not Commercial Mine Ready, S/N: CAT88748TB1P88663 Right Handside Front and Rear Wheel Brake Hydraulic Leak (Inspection Recommended)	1, 2, 3, 4, 5, 7, 9, 17, 19, 20, 26, 27, 28, 31
71	1	Telehandler - Merlo, P38.13 - YOM: 2007 Enclosed Cabin, Air Conditioned ROPS/FOPS: Yes Colour: Green Diesel Hours: 5827 Notes: TARE: 8700Kgs, Max. Lift: 3800Kgs. CB Radio Good Battery Attachments: Forklift Tines THIS LOT CAN ONLY BE COLLECTED AFTER 1PM SATURDAY 9TH FEBRUARY	1, 2, 3, 4, 5, 7, 9, 17, 19, 20, 26, 27, 28, 31
72	1	Telehandler Jib - Genie Australia ATS1100. THIS LOT CAN ONLY BE COLLECTED AFTER 1PM SATURDAY 9TH FEBRUARY	7, 17, 19

LOT	QTY	DESCRIPTION	RISK CODE
73	1	Vibratory Sheep's Foot Roller - Zuzhou, XS120PD - DOM: 09/2007 Enclosed Cabin, Air Conditioned Colour: Yellow Engine Make: Cummins Engine Model: B59C Horsepower: 113Kw Diesel Hours: 1500 Tyres: Front - Good, Rear - Poor Notes: Flat Battery, No Key, Unlocked TARE: 13.8T, S/N: 1121070057	1, 2, 3, 4, 5, 7, 9, 17, 19, 20, 26, 27, 28, 31
73A	1	Service Truck - Ford Stirling (L Ser) - DOM: 1998 Plant ID: SV047 (From Provided Records) Reg No: ZUW517 (VIC) (From Provided Records) Reg Exp: Cancelled 07/06/2016 Odo: assumed 700-800,000 GVM: 24,000kg Additional Information: Has blown Allison Transmission Notes: Service back with Oil Lines. S/N: 6FPAAAAHB6WU55556 (From Provided Records) INSPECTION RECOMMENDED - INVERELL TRUCK & DIESEL REPAIRS	1, 2, 3, 4, 5, 7, 9, 17, 19, 20, 26, 27, 28, 31
74	1	Light Tower - OG Industries Australia/ JLG, 4108 - AN - DOM: 2010 Plant ID:EL0037 Registration No: 5193 TAZ (SA) HRS: 3642, S/N: 6J5PLJL01AP00067	1, 2, 5, 23, 26, 27
75	1	Light Tower - OG Industries Australia/ JLG, 4108 - AN - DOM: 2010 Plant ID: EL0030 Registration No: 5192 TAZ (SA) HRS: 3137, S/N: 6J5PLJL01AP00062, Advised Non Operational	1, 2, 5, 23, 26, 27
76	1	Motor Vehicle - Toyota, Hilux SR - DOM: 10/2008 Dual Cab Chassis Colour: White 4WD 3.0L Engine, D4D Diesel 5 Speed Manual Transmission Reg. No: 091WLQ (QLD) Odometer: 312,271 Km Front Tyre Size: 16" Front Tyre Wear Remaining: 40% Rear Tyre Size: 16" Rear Tyre Wear Remaining: 40% Minor Rust (Major Rust on Tray) Notes: Cabin Radio, Roll Bar, Low Fuel, 5 Seater, Base Model, Bull Bar, Side Steps S/N: VIN: MR0FZ22G401020799	1, 2, 5, 7, 26, 27, 28, 31
77	1	Motor Vehicle - Toyota, Hilux SR - DOM: 08/2007 Dual Cab Chassis Colour: White 4WD 3.0L Engine, D4D Engine Fuel: Diesel 5 Speed Manual Transmission Reg. No: 017WLQ (QLD) Odo: 242,493 Kms Front Tyre Size: 16" Front Tyre Wear Remaining: 40% Rear Tyre Size: 16" Rear Tyre Wear Remaining: 40% Surface Rust Notes: Cabin Radio, Roll Bar, 1/4 Fuel, 5 Seater, Base Model, Bull Bar Mine Spec: Stickers VIN: MR0FZ22G901155566	1, 2, 5, 7, 26, 27, 28, 31
78	1	Generator - Cummins, C350DS - DOM: 2007, Hours: 15000 (Estimated), PCC2100 Digital Control system, Indicated 24v Starter, 6cyl Turbo Diesel, No Power, 350KVA, S/N: 701375	1, 2, 5, 7, 9, 14, 25, 28
79	1	Generator/Welder - Danyo, DCW 4505 - DOM: 2014, 23.7 Kw	1, 2, 5, 7, 9, 14, 25, 28
80	1	Generator - Kubota, KJ-T18OVX50 - Hours: 3744, 14.4Kw, S/N: 271001RT	1, 2, 5, 7, 9, 14, 25, 28
81	1	Distribution Board - JAX Electrical Services, DOM: May 2016 Rated Current: 500AMP Rated Operational Voltage 415V AC Custom Built to Operate Wash Plant, S/N: BG-1631-1	2, 7

LOT	QTY	DESCRIPTION	RISK CODE
82	1	Medium Density Separator - Unbranded, Steel Construction, With 2 x Eriez Vibratory Motors, Some Surface Rust to Unit, Advised Bought New and Not Installed .	1, 2, 3, 4, 6, 7, 9, 14, 15, 20, 28
83	1	Pump - Pioneer Pump, PP4458L7I-EG47 - Engine: Caterpillar C22 15 LPS Impeller Dia: 8.25" Drive Model: C.2.2.T Hour Meter Not Visible S/N: 20785	2, 7, 13, 25, 30
84	1	Separation Plant - Steel Fabricated, Single Vibrating Chamber top infeed, Twin Conical Lower Outfeeds To Steel Hopper	1, 2, 3, 4, 6, 7, 9, 14, 15, 20, 28